

Affected Parts / Materials / Software / Firmware

Table 1 - Required Parts / Materials / Software / Firmware

Description	Part Number	Revision
Igniter Assembly, Setting Tool, 1.4S, 2.95GR	100004220	H

Problem Definition

The current GO style Igniter P/N 100004220 has been manufactured without change for many years. Franklin Applied Physics tested the igniter in December 2017 allowing JRC to advertise the product as 'RF-Safe'.



A copy of the Franklin report can be provided upon request

Procedure

There are no changes to the use or functionality of the GO Igniter

Implementation Assessment

The following documents / procedures will be affected by this bulletin.

- N/A

Applicable Documents

Reference documents needed to complete the procedure

- Regulatory Data Sheet
 - Regulatory Data Sheet will be provided upon request until an update is available for download at www.jetresearch.com

Contacts

For more information concerning this Bulletin, contact the following:

Phone: 817-761-2160
Cell Phone: 817-709-4286
Internet Address: Jerry.tucker@halliburton.com

Jerry Tucker
JRC Sales
8432 South I-35W
Alvarado, TX 76009